


10/508992

1/13

FIG. 1




BEST AVAILABLE COPY

10/508992

2/13

FIG. 2



3/13
FIG. 3

10/508992




FIG. 4





FIG. 7



10/508992

6/13

FIG. 8






FIG. 9



10 / 508992

7/13


FIG. 10



8/13

10/508992


FIG. 11



9/13

10/508992


FIG. 12



10/13

10/508992


FIG. 13



10/508992

11/13


FIG. 14



12/13

10/508992

FIG. 15



10/508992

13/13

Reference numerals in the drawings

- 1 Vibrating linear actuator
- 2 Coil
- 3A Stator
- 4A Mover
- 5 Permanent magnet
- 6 Elastic body
- 22 Driving section
- 25 Zero-cross detector
- 26 Zero-cross monitor
- 27 Output controller

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☒ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY.
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.